

Release Date	Version History	Software Update Tools
15-Oct-18	<p>Wi-Fi v2.1.0</p> <ul style="list-style-type: none"> • Add gapless support for KEF Stream App • Fixed TIDAL unsupported format for some cases <p>MCU v3.0.0, DSP v0.54</p> <ul style="list-style-type: none"> • No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> • LS50_Wireless_Firmware_Update_Tool_V4.0.0 <p>Windows</p> <ul style="list-style-type: none"> • LS50W_FW_Upgrade_Tool_V4.0.0
27-Jun-18	<p>MCU v3.0.0 , Wi-Fi v2.0.0</p> <ul style="list-style-type: none"> • Add TCP/IP control for 3rd party developers • Fixed EQ access issue for certain Android devices <p>DSP v0.54</p> <ul style="list-style-type: none"> • No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> • LS50_Wireless_Firmware_Update_Tool_V3.0.0 <p>Windows</p> <ul style="list-style-type: none"> • LS50W_FW_Upgrade_Tool_V3.0.0
16-April-18	<p>MCU v2.5.0</p> <ul style="list-style-type: none"> • Extended support for programmable IR remote controls (Compatibility refer to FAQ section A12) <p>Wi-Fi v1.2.0</p> <ul style="list-style-type: none"> • Add “QPlay” support for China <p>DSP v0.54</p> <ul style="list-style-type: none"> • No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> • LS50_Wireless_Firmware_Update_Tool_V3.0.0 <p>Windows</p> <ul style="list-style-type: none"> • LS50W_FW_Upgrade_Tool_V3.0.0
15-Nov-17	<p>MCU v2.4.0</p> <ul style="list-style-type: none"> • Fixed low voltage protection issue causing system or slave error <p>Wi-Fi v1.1.6</p> <ul style="list-style-type: none"> • Improved Roon support • Various bug fixes that improve app stability • Bug fixes to improve firmware upgrade stability <p>DSP v0.54</p> <ul style="list-style-type: none"> • No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> • LS50_Wireless_Firmware_Update_Tool_V2.0 <p>Windows</p> <ul style="list-style-type: none"> • LS50W_FW_Upgrade_Tool_V2.0

9-Oct-17	<p>MCU v2.3.0</p> <ul style="list-style-type: none">• Add support to swap between Left and Right speakers <p>Wi-Fi v1.1.4</p> <ul style="list-style-type: none">• Add “Spotify Connect” support (compatibility varies by country) <p>DSP v0.54</p> <ul style="list-style-type: none">• No update	<p>Mac OS X</p> <ul style="list-style-type: none">• LS50_Wireless_Firmware_Update_Tool_V1.3 <p>Windows</p> <ul style="list-style-type: none">• LS50W_FW_Upgrade_Tool_V1.1.0.0
22-May-17	<p>MCU v2.2.1</p> <ul style="list-style-type: none">• Fixed Wi-Fi network memory occasionally lost after system restarting• Fixed potential left speaker no output issue• Each source has now individual volume memory• Add the ability to disable Auto-Standby time• Other bug fixes and improvements <p>Wi-Fi v1.1.3</p> <ul style="list-style-type: none">• Add ALAC format support• Fixed volume control over App issue• Other bug fixes and improvements <p>DSP v0.54</p> <ul style="list-style-type: none">• No update	<p>Mac OS X</p> <ul style="list-style-type: none">• LS50_Wireless_Firmware_Update_Tool_V1.0 <p>Windows</p> <ul style="list-style-type: none">• LS50W_FW_Upgrade_Tool_V1.1.0.0